

Er. M. Balasubramaniam, M.E., (Strs) MIE., FIV., C.Engg.,

BALU RAMANI CONSTRUCTION

- ★ Chartered Engineer ---- 147273-3
- ★ Constructions & Consulting Civil Engineer
- ★ **Govt. Approved** Coimbatore District Collector's Soil Stability Panel Engineer
R.Dis : 7194 / 2017 / C2 - CLASS - 1A
- ★ Licensed Bldg. Surveyor
for Coimbatore Corporation
Reg. No. 246 / 2009 / Grade I.
- ★ Competent Person of
Inspector of Factories
H1/ 2630 / 2018
- ★ **Govt. Regd.** Approved Valuer F-19135
- ★ **Govt. of India** Regd. Valuer for Income Tax & Wealth Tax.
- ★ Panel Valuer Nationalised & Scheduled Bank



Residential & Industrial Building
Engineers & Architects

103, 84-A, Sarojini Circle
Senkadu, Kattoor

Near by Women's Polytechnic
P.N. Palayam, Coimbatore - 641 012

E-mail : ramanicivil88@yahoo.com
reach3balu@gmail.com

Mobile : 98431 23456

STABILITY CERTIFICATE FORM - A

1. Door Number of building .. Maharishi International School.
2. Location (Street Number, Ward .. S.F.No:30/7,ZaminMuthurVillage,
Number Name of Place, ie. Corporation, Pollachi Taluk,Coimbatore Dist.
Municipality / Panchayat Union
/Township/Cantonment Coimbatore
3. By Whom Managed .. The Correspondent.
4. Details of the building in the campus . School Purpose. (CBSE &IS)
5. Condition of the building .. Good.
Year of Construction & Age .. 2017 & 2018.
6. Authority who have approved the
Construction from structural point of view ..yes.



[Handwritten signature]

TO WHOMSOEVER IT MAY CONCERN

This is to certify that for the Maharishi International School S.F.No:30/7,
Zamin Muthur Village, Pollachi Taluk, Coimbatore Dist.

Place : Coimbatore

Date : 02.05.2019.



R. Agneswari

MAHARISHI INTERNATIONAL SCHOOL
Palakkad Road, Zamin Muthur,
Pollachi - 642 005.

M. Balasubramaniam

M. BALASUBRAMANIAM, ME(Strsr)..MIE,FI
STRUCTURE & SOIL STABILITY BANK VA
COLLECTOR'S PANEL ENGINEER CLAS
103, 84-A, Sarojini Complex,
Senkadu, Kattoor Street,
Near by Womens Polytechnic Col
P.N. Palayam, Coimbatore - 641
Mobile No: 98432 65083

R. Lakshmi
PRINCIPAL

MAHARISHI INTERNATIONAL SCHOOL
Palakkad Road, Zamin Muthur,
POLLACHI - 642 005,

Er. M. Balasubramaniam, M.E., (Strs) MIE., FIV., C.Engg.,

BALU RAMANI CONSTRUCT

- ★ Chartered Engineer ---- 147273-3
- ★ Constructions & Consulting Civil Engineer
- ★ **Govt. Approved** Coimbatore District Collector's Soil Stability Panel Engineer
R.Dis : 7194 / 2017 / C2 - CLASS - 1A
- ★ Licensed Bldg. Surveyor
for Coimbatore Corporation
Reg. No. 246 / 2009 / Grade I.
- ★ Competent Person of
Inspector of Factories
H1/ 2630 / 2018
- ★ **Govt. Regd.** Approved Valuer F-19135
- ★ **Govt. of India** Regd. Valuer for Income Tax & Wealth Tax.
- ★ Panel Valuer Nationalised & Scheduled Bank



Residential & Industrial Buildings
Engineers & Valuers

103, 84-A, Sarojini Complex,
Senkadu, Kattor Street

Near by Women's Polytechnic College,

P.N. Palayam, Coimbatore - 641 037

E-mail : ramanicivil88@yahoo.com

reach3balu@gmail.com

Mobile : 98432XXXXXX

DECLARATION

I, **Er.M.BALASUBRAMANIAM, M.E., (Strul). Fiv., MIE., C.Engg.** Balu Ramani Constructions, Residential & Industrial buildings Engineers & Valuers, 103, 84-A, Sarojini Complex, Senkadu, Kattor Street, Near by Womens Polytechnic College, P.N.Palayam, Coimbatore-641 037, do hereby declare that I possess the qualification and experience specified in the Table to rule 11 of the Madras Public Building (Licensing) Rules 1966 for issuing the certificate structural Soundness of the Building covered by the certificate.

1. Name and Address of the Collectors Panel Engineer : **Er.M.Balasubramaniam, M.E. (Strul) Fiv., MIE., C.Engg. Balu Ramani Constructions, Residential & Industrial buildings Engineers & Valuers, 103, 84-A, Sarojini Complex, Senkadu, Kattor Street, Near by Womens Polytechnic College, P.N.Palayam, Coimbatore-641 037.**
2. Engineering Qualification : **M.E (Strul) Fiv., MIE., C.Engg**
3. Coimbatore District Collector's Stability Panel Engineer : **R.Dis.7194/2017/C2**
4. Number of years of experience and nature thereof : **A total of 25 years experience in Construction field (Designing and Execution of Multistoried framed structures including 4 years service in Foreign Countries)**

Station : Coimbatore

.3.

- | | | | |
|-----|--|----|--------------|
| 13. | Fire protection
The suitable provisions made
by way of fire fighting appliances | .. | Provided. |
| 14. | If they are adequate in regard to
entrance to exist for the emergencies | .. | Yes. |
| 15. | General remarks | .. | Good. |
| 16. | Approximate cost of building | .. | Rs 3.5 C. |
| 17. | Area of the building in all Floors | .. | 25496 Sq ft. |

Date : 02.05.2019.

Place : Coimbatore.



R. Abagesudan

MAHARISHI INTERNATIONAL SCHOOL
Palakkad Road, Zamin Muthur,
Pollachi - 642 005.

R. Lalitha
PRINCIPAL

MAHARISHI INTERNATIONAL SCHOOL
Palakkad Road, Zamin Muthur,
POLLACHI - 642 005.

M. Balasubramaniam
M. BALASUBRAMANIAM, ME(Strsr), MIE, F.
STRUCTURE & SOIL STABILITY BANK V
COLLECTOR'S PANEL ENGINEER CLAS
103, 84-A, Sarojini Complex
Senkadu, Kattoor Street,
Womens Polytechnic Co
P.N. Palayam, Coimbatore - 641
Mobile No: 98432 65083

7. Details of construction of the building
(particulars of the foundation soil,
specification of the various parts under)
- | | | | |
|----|-----------------|---|---|
| 1. | Foundation | . | RCC Footing Structure. |
| 2. | Basement | . | R.R.Masonry Footing&CR |
| 3. | Super Structure | . | Brick screen wall in CM |
| 4. | Floor and roof | . | RCC Roof & Vitrified Tiles Flooring. |
| 5. | No of Stories | . | Ground, First Floor.
&RCC Framed Building. |
8. Any partition walls intermediate
Floor which do not have proper support .. Nil
9. **Verandah pillars:**
- | | | | |
|----|----------------------|----|--------|
| a. | Structural Soundness | .. | Sound. |
| b. | Present condition | .. | Good |
10. **Beams, joints etc & Rafters**
- | | | | |
|----|----------------------|----|--------|
| a. | Structural soundness | .. | Sound. |
| b. | Present condition | .. | Good |
11. **Roof:**
- | | | | |
|----|----------------------|----|--------|
| a. | Structural soundness | .. | Sound. |
| b. | Present condition | .. | Good. |
12. i. **Miscellaneous items**
- | | | | |
|----|---------------------------------------|----|--------|
| a. | Stair case | .. | Good. |
| b. | Present condition & width
of stair | .. | Good. |
| c. | Structural soundness | .. | Sound. |
- ii. **Balconies**
- | | | | |
|----|-------------------------|----|--------|
| a. | Are they adequate width | .. | Good. |
| b. | Structural soundness | .. | Sound. |
| c. | Present condition | .. | Good. |
- iii. **Electrical installation:**
- | | | | |
|----|-------------------------------------|----|--------------------------|
| a. | Present condition | .. | Good |
| b. | Concealed wiring or
open wiring. | .. | Open & Concealed wiring. |



Handwritten signature and date: 3/11/2007